

DOUBLE CHECK VALVE ASSEMBLY
OUTDOOR HORIZONTAL INSTALLATION



DOUBLE CHECK VALVE ASSEMBLY
PIT INSTALLATION

DATE	REVISION	BY

DOUBLE CHECK VALVE TYPICAL INSTALLATION

EPHRATA PUBLIC WORKS DEPARTMENT

DRAWN
CHECK
SCALE NTS
DATE 12/20/10

CITY OF EPHRATA
GRANT COUNTY WASHINGTON

I-1